

CONVAIR
A Division of General Dynamics Corporation
(San Diego)

DESIGN INFORMATION BULLETIN

NO.: 26.003


CONVAIR REPORT NO. ZM-22-005

PAGE: 1 of 2

MODEL 22 AIRPLANE

CORONA DISCHARGE CONTROL
H.F. ANTENNA SYSTEM

DATE: 8-14-57



The above represents the minimum requirements for the control of corona discharge phenomenon in the immediate vicinity of the high frequency antenna isolation gap in the vertical stabilizer.

C O N V A I R
A Division of General Dynamics Corporation
(San Diego)

DESIGN INFORMATION BULLETIN

NO.: 26.003

CONVAIR REPORT NO. ZM-22-005

PAGE: 2 of 2

MODEL 22 AIRPLANE

DATE: 8-14-57

CORONA DISCHARGE CONTROL

H.F. ANTENNA SYSTEM

P. M. Keeler

P. M. Keeler
Antenna Laboratory

A. J. Savard

A. J. Savard
Project Engineer

W. Garcia

W. Garcia
Electronics Group

G. G. Green

G. G. Green
Chief, Structures

J. Sikes

J. Sikes
Wing & Tail Group

R. W.